


BRITISH COLUMBIA

AERODROME / FACILITY DIRECTORY

TERRACE BC

CYXT



REF	N54 28 07 W128 34 42 3S 19°E (2014) UTC-8(7) Elev 713' A5013 LO1 HI3 CAP
OPR	Terrace-Kitimat Aprt Society 250-635-2659 13-08Z± Cert
PF	A-1,2,3,6,7 C-4,5
FLT PLN	
FIC	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)
WX	METAR H24. TAF H24, issue times: 01, 07, 13, 19Z.
SERVICES	
FUEL	100LL, JA-1 (FSII avbl) 1230-0400Z±, 250-638-1564, O/T call out chg may be levied.
OIL	All
S	5 May 01-Oct 31
ARFF	DESIGNATED CAT 6 1330-0740Z± for scheduled commercial acft 20 seats & abv, other acft 2 hr PN 250-615-7636. Call out chg.
PVT ADV	Executive Flight Centre 250-638-1564 Fax 250-638-1589
MILCON	Executive Flight Centre Fuel 250-638-1564

BRITISH COLUMBIA

AERODROME / FACILITY DIRECTORY

TERRACE BC (Cont'd)		CYXT
RWY DATA	Rwy 15(153°)/33(333°) 7497x148 ASPH Rwy 03(033°)/21(213°) 5316x148 ASPH Thld 21 displ 797' Rwy 21 down 0.69% Rwy 15 RVR 1200(1/4sm) Day only/Rwy 33 RVR 1200(1/4sm) Day only AGN IV Rwy 03/21 AGN IIIA	
RWY CERT	Twy: A, B AGN IIIB	
TWY CERT	Twy B uncontrolled first 2000' fr apron	
TWY	Tran acft must park in SE corner of Apron. Itinerant parking with tiedowns on grass	
APRON	May to Oct. N side main apron stands 1-3 are rstd to sked tfc only. All stands PPR. Itinerant pilot/pax access via pilot access door on E end of tml bldg. No access/egress via tml bldg facility is permitted. Exceptions require prior approval of aprt opr. Corporate itinerant prkg ctc Executive Flight Centre.	
RCR	Opr Win maint 13-08Z± O/T 2 hrs PN 250-615-7636, cost recovery. Rwy 03/21 no win maint. Ltd hrs CRFI, PCN	
LIGHTING	15-AO(TE HI) P2 3.5°, 33-AN(TE HI) P2 3.5° ARCAL-122.0 type K PAPI limitation/restriction. PAPI Rwy 33 to be used only within 2NM of thld.	
COMM	122.0 PTC avbl (E) (emerg only 250-635-2110)	
RADIO	Pacific rdo 123.375(FISE) 126.7 (bcst)	
RCO	rdo 122.0 5NM 3700 ASL (CAR 602.98)	
MF	Vancouver Ctr 128.4 269.1	
PAL		
NAV	XT 332 (M) N54 22 27 W128 35 04 KITIMAT ZKI 203 (M) N54 03 15 W128 40 12	
NDB	IXT 110.1 Ch 38 N54 27 39 W128 35 16	
DME	IXT 110.1 (Rwy 33)	
ILS		
PRO	Rgt hand circuits Rwy 33 (CAR 602.96). Ngt circuit pro, see VTPC.	
CAUTION	Ngt ops not recommended unless all hazard bcns are oprg. Recommend that only pilots familiar with the local area use the aprt dur the hrs of darkness. Hi terrain reduces operational length of Rwy 33 PAPI. Displ thld 21 marked by hi vis barrels.	