


ONTARIO

AERODROME / FACILITY DIRECTORY

**OWEN SOUND (COOK FIELD) ON**

**CCK5**

<b>REF</b>	N44 38 05 W80 44 45 10E 10°W (2011) UTC-5(4) Elev 1040' A5000
<b>OPR</b>	Jim Cook 519-379-4964 Reg PPR
<b>PF</b>	B-1 D-2,3,4,5,6
<b>FLT PLN</b>	
<b>FIC</b>	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
<b>RWY DATA</b>	Rwy 09(092°)/27(272°) 2191x80 GRASS
<b>RCR</b>	Ltd hrs. No win maint. Rwy soft in spring.
<b>COMM</b>	
<b>ATF</b>	tfc 123.0 3NM 4100 ASL
<b>PRO</b>	Recommend W dep, rising terrain to the E.
<b>CAUTION</b>	Drainage ditch on either side of centre of rwy.



**ONTARIO**

AERODROME / FACILITY DIRECTORY

---

**OWEN SOUND / BILLY BISHOP REGIONAL ON** — See MEAFORD / MAJOR-GENERAL RICHARD ROHMER

---

---