

BRITISH COLUMBIA

AERODROME / FACILITY DIRECTORY

FAIRMONT HOT SPRINGS BC

CYZ

REF	N50 19 49 W115 52 24 15°E (2013) UTC-7(6) Elev 2661' A5005 LO2 HI3 CAP RCAP
OPR	APM 250-341-7150 Columbia Valley Airport Society 250-345-2121 Reg Ldg fees
PF	B-1 C-2,5 D-3,4,6
FLT PLN	
FIC	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)
WX	AUTO 250-345-6361 H24 (see COMM)
SERVICES	1530-0430Z± Apr 1-Sep 30, 1530-2130Z± Oct 1-Mar 31 O/T call out chg levied
FUEL	100LL, JA (FSII avbl), SP
OIL	All
S	4,5,6
RWY DATA	Rwy 16(156°)/34(336°) 6005x100 ASPH Thld 34 displ 821' Rwy 16 up 0.4% AGN II
RCR	Opr Ltd win maint
LIGHTING	16-AS(TE LO) P2, 34-AS(TE LO) P2 PAPI Rwy 16 offset 12° rgt. ARCAL-123.2 type K. ARCAL opr A/D beacon.
COMM	
RCO	Pacific rdo (Invermere) 123.475 (FISE) 126.7 (bcst)
ATF	tfc 123.2 5NM 5700 ASL
AUTO	122.975
PRO	Rgt hand circuits rwy 16 (CAR 602.96).
CAUTION	Hwy overpass & p-line aprx 40 AGL crosses apch Rwy 34 aprx 1250' fr rwy thld. Extensive glider activity over mtns to E of A/D. Recommend only pilots familiar with lcl area use this apt dur hrs of darkness. Extv bird activity in vic of rwy.

