



BRITISH COLUMBIA

AERODROME / FACILITY DIRECTORY

VICTORIA HARBOUR (CAMEL POINT) BC (Heli)

CBF7



REF	N48 25 05 W123 23 17 Adj 17°E (2013) UTC-8(7) Elev 15' VTA A5004 CAP
OPR	Pacific Heliport Services 250-386-7676 Cert Ldg fees PPR (see Restriction 1 in PRO).
PF	A-1 C-2,3,4,5,6
FLT PLN	
FIC	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)
ACC	Vancouver IFR 604-586-4590/4591 or 800-668-1333; IFR tng flts PPR ctc 604-586-4592 or 800-668-1333.
SERVICES	1430-0330Z† Mon-Fri, 1500-0215Z† Sat-Sun & hol(s) exc clsd Dec 25 & Jan 1
FUEL	JA-1 (FSII avbl)
S	4
HELI DATA	FATO/TLOF 112' dia CONC/ASPH Safety Area 149' dia 20,500 lbs Max heli overall length 73' Parking Pad 1: 53' dia CONC/ASPH 15,400 lbs Parking Pad 2: 53' dia CONC/ASPH 15,400 lbs Parking Pad 3: 73' dia CONC/ASPH 20,500 lbs Parking Pad 4: 53' dia ASPH. 15,400 lbs. Day use tkof/lgd, hover, taxi & prkg only. Ngt use parking only (CAR 602.96).
APRON	Prkg fees; ctc opr
RCR	Opr
LIGHTING	RW(LO) green LED

BRITISH COLUMBIA

AERODROME / FACILITY DIRECTORY

VICTORIA HARBOUR (CAMEL POINT) BC (Heli) (Cont'd) CBF7

COMM	RADIO Harbour rdo 127.45 (V) 1345-0530Z± (emerg only 250-953-1500) RCO Pacific rdo 125.85 (FISE) ATIS Victoria Harbour 120.0 14-05Z± MF/ATF Harbour rdo 1345-0530Z± O/T Harbour tfc 127.45 5NM 2500 ASL within Victoria Harbour CZ (CAR 602.98) ARR Victoria Tml 125.95 DEP Victoria Tml 125.95
PRO	Arr/dep 232° to 312° fr heli, slope 8% (H3) (see Victoria Harbour VTPC). Procedures for crossing the southern Strait of Georgia within Tml Class C airspace refer to Vancouver Intl, VTPC for Crossing the Southern Strait of Georgia. Pads 3 & 4 preferred for itinerant use. Pads 1 & 2 used for scheduled service. Restrictions: 1.Pursuant to CAR 602.96(3)(d), prior permission required from Victoria Harbour (Camel Point) Heliport Manager 250-386-7676, 604-688-4646 or 604-273-4688. 2.Pursuant to CAR 602.96(3)(d), unless otherwise auth by Heli mgr, tkofs or ldgs outside of normal staffed hours of operation are not permitted.