

BRITISH COLUMBIA

AERODROME / FACILITY DIRECTORY

FAIRMONT HOT SPRINGS BC

CYCZ

REF	N50 19 49 W115 52 24 15°E (2013) UTC-7(6) Elev 2661' A5005 LO2 HI3 RCAP
OPR	Columbia Valley Airport Society 250-345-2121 Reg Ldg fees
PF	B-1 C-2,5 D-3,4,6
FLT PLN	
FIC	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)
SERVICES	1530-0430Z± Apr 1-Sep 30, 1530-2130Z± Oct 1-Mar 31 O/T call out chg levied
FUEL	100LL, JA (FSII avbl), SP
OIL	All
S	4,5,6
RWY DATA	Rwy 16(156°)/34(336°) 6005x100 ASPH Thld 34 displ 821'. Rwy 16 up 0.4%.
RCR	Opr Ltd win maint
LIGHTING	16-AS(TE LO) P2, 34-AS(TE LO) P2 PAPI Rwy 16 offset 12° rgt. ARCAL-123.2 type K. ARCAL opr A/D beacon.
COMM	
RCO	Pacific rdo (Invermere) 123.475 (FISE) 126.7 (bcst)
ATF	tfc 123.2 5NM 5700 ASL
NAV	
NDB	D6 261 (L) N50 19 37 W115 52 36 Pvt
PRO	Rgt hand circuits rwy 16 (CAR 602.96).
CAUTION	Hwy overpass & p-line aprx 40 AGL crosses apch Rwy 34 aprx 1250' fr rwy thld. Extensive glider activity over mtns to E of A/D. Recommend only pilots familiar with lcl area use this apt dur hrs of darkness. Ngt ops not recommended unless all 4 hazard beacons oprg. Extv bird activity in vic of rwy.

