

**ONTARIO**

**AERODROME / FACILITY DIRECTORY**

**ATIKOKAN MUNI ON**

**CYIB**

<b>REF</b>	N48 46 27 W91 38 20 1NW 2°W (2013) UTC-5 Elev 1409' A5001 A5008 LO4 CAP
<b>OPR</b>	Township 807-597-1234 or Fax 807-597-6186 Reg
<b>PF</b>	A-1 C-2,3,4,5,6
<b>FLT PLN</b>	Pilots to open/close VFR fit plan with London rdo, FISE or by phone
<b>FIC</b>	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
<b>SERVICES</b>	Call out chg may be levied for one or more svcs.
<b>FUEL</b>	100LL, Jet A PN 807-597-2135 or Opr, 12-19Z ‡ Mon-Fri exc hol.
<b>RWY DATA</b>	Rwy 04(040°)/22(220°) 3495x100 asphalt Rwy 04 up 0.69% AGN IIIA
<b>RCR</b>	Opr Ltd win maint. Thld rwy 22 turnaround area deteriorates in spring & fall.
<b>LIGHTING</b>	04-(TE LO) V1, 22-(TE LO) V1 ARCAL-122.3 type J
<b>COMM</b>	
<b>RCO</b>	London rdo 123.275 (FISE) 126.7 (bcst)
<b>MF</b>	tfc 122.3 (no ground station) 5NM 4500 ASL (CAR 602.98)
<b>PRO</b>	Rgt hand circuits Rwy 22 (CAR 602.96).
<b>CAUTION</b>	Aprt vehicles not radio-equipped. Extv bird activity in vic of rwy Oct-Dec.

