


CANADA FLIGHT SUPPLEMENT / GPH 205

Effective 0901Z 17 June 2021 to 0901Z 12 August 2021

AERODROME/FACILITY DIRECTORY B785


OWEN SOUND / BILLY BISHOP REGIONAL ON

CYOS

REF	N44 35 26 W80 50 18 3E 10°W UTC-5(4) Elev 1008' A5000 LO4 LO6 CAP	
OPR	City of Owen Sound 519-371-6936 Reg	
PF	A-1,2,7 C-3,4,5,6	
CUST	AOE/15 888-226-7277 13-21Z‡ Mon-Fri exc hols	
FLT PLN	FIC London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	
SERVICES	13-21Z‡ O/T call out chg 2 hrs PN	
FUEL	100LL, JA-1, SP	
OIL	Aeroshell 15W50, W80, W100	
S	2,4,5	
RWY DATA	Rwy 18(181°)/36(001°) 3933x75 asphalt Rwy 18, first 1849' 1.0% down, last 2083' 0.9% up	
RCR	Opr	
LIGHTING	18-(TE LO) AP, 36-(TE LO) AP ARCAL-123.0 type J	
COMM	ATF UNICOM (AU) ltd hrs O/T tfc 123.0 5NM 4000 ASL	
PRO	Rgt hand circuits Rwy 36 (CAR 602.96).	
CAUTION	331' twr 1.2NM W of rwy. Wildlife frequently on rwy.	

OWEN SOUND (COOK FIELD) ON

CCK5

REF	N44 38 05 W80 44 45 10E 10°W (2011) UTC-5(4) Elev 1040' A5000	
OPR	Jim Cook 519-379-4964 Reg PPR	
PF	B-1 D-2,3,4,5,6	
FLT PLN	FIC London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	
RWY DATA	Rwy 09(092°)/27(272°) 2191x80 turf	
RCR	Ltd hrs. No win maint. Rwy soft in spring.	
COMM	ATF tfc 123.0 3NM 4100 ASL	
PRO	Recommend W dep, rising terrain to the E.	
CAUTION	Drainage ditch on either side of centre of rwy.	