

## BRITISH COLUMBIA

## AERODROME / FACILITY DIRECTORY

## FORT ST. JOHN BC

CYXJ

<b>REF</b>	N56 14 18 W120 44 25 3.8E 17°E (2020) UTC-7 Elev 2280' A5014 A5022 LO1 HI2 HI3 CAP	
<b>OPR</b>	North Peace Aprt Svcs Ltd 250-787-0426 H24 Cert Ldg fees	
<b>PF</b>	A-1,2,3,6 C-1,2,3,4,5,6	
<b>FLT PLN</b>	<b>FIC</b> Edmonton 866-WXBRIEF (Toll free within Canada) or 866-541-4102 (Toll free within Canada & USA) <b>ACC WX</b> Edmonton IFR 888-358-7526 METAR H24. TAF H24, issue times: 01, 07, 13, 19Z.	
<b>SERVICES</b>	<b>FUEL</b> 100LL, JA-1 (FSII avbl), HPR <b>OIL</b> All <b>S</b> 1,2,3,4,5,6 <b>ARFF</b> DESIGNATED CAT 6 1200-0730Z sked pax flt only, O/T 2 hr PN. 250-261-8897 cost recovery <b>SUP FL</b> D & A-ice <b>JASU</b> Elec Start 28v-800 Amp, 28v-1500 amp, CE15 <b>PVT ADV</b> Executive Flight Centre 122.35 250-785-6174 <b>MIL CON</b> Executive Flight Centre Aviation Ltd 250-785-6174	
<b>RWY DATA</b>	Rwy 12(118°)/30(298°) 6909x150 ASPH Rwy 30 up 0.53% first 1900' Rwy 03(028°)/21(208°) 6698x148 ASPH Thld 21 displ 196' Rwy 03 up 1.50% first 3000' Rwy 21 first 3700' down 0.65%	
<b>RWY CERT</b>	Rwy 12 RVR 1200(1/4sm)/Rwy 30 RVR 1200(1/4sm) AGN IIIB	
<b>RCR</b>	Rwy 03/21 not avbl for acct when RVR below 2600(1/2sm) (CAR 602.96) AGN IIIB Opr Ltd win maint 1200-0730Z, O/T 2hrs PN, call out chg may be levied. CRFI, PCN.	
<b>LIGHTING</b>	03-AS(TE ME) P2, 21-AO(TE ME) P2, 12-AO(TE HI) P2, 30-AN(TE HI)	
<b>COMM</b>	<b>RADIO</b> 118.5 (E) (emerg only 250-787-0434) <b>RCO</b> Edmonton rdo 123.55 (FISE) 126.7 (bcst) <b>ATIS</b> 128.5 ltd hrs <b>CLNC DEL</b> 121.9 PTC avbl ltd hrs <b>MF</b> rdo 118.5 5NM 5300 ASL (CAR 602.98) <b>PAL</b> Edmonton Ctr 132.6 285.4	
<b>NAV</b>	<b>VOR/DME</b> YXJ 114.2 Ch 89 N56 17 03 W120 53 44 (2664°) <b>ILS</b> IXJ 109.5 (Rwy 30) RVR	
<b>CAUTION</b>	Aerobatics may be in progress over aprt 6000 ASL & below.	