

KEMESS CREEK BC

CBQ7

REF	N56 58 28 W126 44 27 18°E (2025) UTC-8(7) Elev 4191' A5022 LO1 RCAP	
OPR	AuRico Gold Inc. Kemess Mine 778-724-4428/4425 Reg PPR	
FLT PLN		
FIC	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)	
WX	ALTIMETER/WIND 778-724-4428 ltd hrs (see COMM)	
RWY DATA	Rwy 11(110°)/29(290°) 4671x75 GRVL	
RCR	Opr Regular sum maint (grading, packing), ltd win maint.	
LIGHTING	11-(TE ME) P1 3.0°, 29-AS AO(TE ME) P1 4.5° PAPI limitation/restriction. PAPI Rwy 11 to be used only within 3NM of thld; PAPI Rwy 29 to be used only within 2NM of thld ARCAL-122.7 type K	
COMM		
ATF	UNICOM (AU) ltd hrs O/T tfc 122.7 5NM 7200 ASL	
PRO	Rgt hand circuits Rwy 11 (CAR 602.96)	
CAUTION	Higher terrain on apch near thld of Rwy 29. Only pilots familiar with lcl terrain should use this A/D dur hrs of darkness. Ngt ops not recommended unless both hazard bcns oprg. Hi terrain reduces operational lengths of Rwys 11 and 29 PAPI.	