

MONT-LAURIER QC

CSD4

REF	N46 33 53 W75 34 34 3W 14°W (2013) UTC-5(4) Elev 815' A5000 A5002 LO6 LO7 CAP	
OPR	Association des Pilotes et Propriétaires d'aéronefs 819-623-5475 Reg	
PF	A-1,2 C-3,4,5,6,7,8	
FLT PLN	(bil)	
FIC	Québec 866-GOMÉTÉO or 866-WXBRIEF (Toll free within Canada) or 866-541-4105 (Toll free within Canada & USA)	
ACC	Montréal 800-633-1353	
WX	AUTO (see COMM) WxCam	
SERVICES	13-22Z± O/T ctc opr	
FUEL	100LL, JA-1 (FSII avbl)	
OIL	15W50	
S	1,2,4,5,6	
RWY DATA	Rwy 08(077°)/26(257°) 4002x75 ASPH Thld 08 displ 197' AGN IIIA	
RCR	Opr Expect delays for snow removal.	
LIGHTING	08-(TE ME), 26-(TE ME) P1 (no setting to ME) ARCAL-122.8 type J	
COMM		
RCO	(bil) Québec rdo (Mont-Laurier) 123.475 (FISE)	
ATF	UNICOM ltd hrs O/T tfc 122.8 5NM 3900 ASL	
PAL	(bil) Montréal Ctr 126.575	
AUTO	123.425 (French)	
CAUTION	Possibility of deer on rwy.	