


QUEBEC

AERODROME / FACILITY DIRECTORY

MATAGAMI QC

CYNM

REF	N49 45 42 W77 48 10 6W 14°W (2013) UTC-5(4) Elev 918' A5009 LO3 LO7 HI1 HI4 CAP	
OPR	Ministère des transports et de la mobilité durable 819-739-2926/8141 Reg	
PF	A-1 D-2,3,4,5,6	
FLT PLN	(bil)	
FIC	Québec 866-GOMÉTÉO or 866-WXBRIEF (Toll free within Canada) or 866-541-4105 (Toll free within Canada & USA)	
ACC	Montréal 800-633-1353	
WX	METAR AUTO H24 (see COMM) WxCam	
SERVICES	O/T call out chgs	
FUEL	100LL, JA-1 1130-2100Z± ctc 819-739-2926 O/T 819-739-8141	
RWY DATA	Rwy 15(148°)/33(328°) 5001x100 ASPH Rwy 15 down 0.5% first half Rwy 33 down 0.84% first half AGN IIIA	
RCR	Opr 12-23Z± Mon-Fri O/T 3 hr PN 819-739-8141 CRFI PCN	
LIGHTING	15-AS(TE ME) P2, 33-AO(TE ME) ARCAL-122.8 type K	
COMM	(bil) Québec rdo 123.55 (FISE) 126.7 (bcst) tfc 122.8 5NM 4000 ASL	
DRCO	127.45 (English), 125.3 (French)	
ATF		
AWOS		
CAUTION	Wildlife and migrating birds in vic of rwy. Ctc opr. ABN not visible on apch Rwy 15 due to trees.	