

BRITISH COLUMBIA

AERODROME / FACILITY DIRECTORY

FORT ST. JOHN BC

CYXJ

REF	N56 14 18 W120 44 25 3.8E 17°E (2020) UTC-7 Elev 2280' A5014 A5022 LO1 HI2 HI3 CAP	
OPR	North Peace Aprt Svcs Ltd 250-787-0426 H24 Cert Ldg fees	
PF	A-1,2,3,6 C-1,2,3,4,5,6	
FLT PLN	<p>FIG Edmonton 866-WXBRIEF (Toll free within Canada) or 866-541-4102 (Toll free within Canada & USA)</p> <p>ACC WX Edmonton IFR 888-358-7526 METAR H24. TAF H24, issue times: 01, 07, 13, 19Z.</p>	
SERVICES	<p>FUEL 100LL, JA-1 (FSII avbl), HPR</p> <p>OIL All</p> <p>S 1,2,3,4,5,6</p> <p>ARFF DESIGNATED CAT 6 1200-0730Z sked pax flt only, O/T 2 hr PN. 250-261-8897 cost recovery</p> <p>SUP FL D & A-ice</p> <p>JASU Elec Start 28v-800 Amp, 28v-1500 amp, CE15</p> <p>PVT ADV Executive Flight Centre 122.35 250-785-6174</p> <p>MIL CON Executive Flight Centre Aviation Ltd 250-785-6174</p>	
RWY DATA	<p>Rwy 12(118°)/30(298°) 6909x150 ASPH Rwy 30 up 0.53% first 1900'</p> <p>Rwy 03(028°)/21(208°) 6698x148 ASPH Thld 21 displ 196' Rwy 03 up 1.50% first 3000' Rwy 21 first 3700' down 0.65%</p>	
RWY CERT	<p>Rwy 12 RVR 1200(1/4sm)/Rwy 30 RVR 1200(1/4sm) AGN IIIB</p> <p>Rwy 03/21 not avbl for act when RVR below 2600(1/2sm) (CAR 602.96) AGN IIIB</p> <p>Opr Ltd win maint 1200-0730Z, O/T 2hrs PN, call out chg may be levied. CRFI, PLR/PCN.</p>	
LIGHTING	<p>03-AS(TE ME) P2, 21-AO(TE ME) P2, 12-AO(TE HI) P2, 30-AN(TE HI)</p>	
COMM	<p>RADIO 118.5 (E) (emerg only 250-787-0434)</p> <p>RCO Edmonton rdo 123.55 (FISE) 126.7 (bcst)</p> <p>ATIS 128.5 ltd hrs</p> <p>CLNC DEL 121.9 PTC avbl ltd hrs</p> <p>MF rdo 118.5 5NM 5300 ASL (CAR 602.98)</p> <p>PAL Edmonton Ctr 132.6 285.4</p>	
NAV	<p>VOR/DME YXJ 114.2 Ch 89 N56 17 03 W120 53 44 (2664')</p> <p>ILS IXJ 109.5 (Rwy 30) RVR LOC reliable only within 10° either side of centreline.</p>	
CAUTION	<p>Aerobatics may be in progress over aprt 6000 ASL & below.</p>	