


ONTARIO

AERODROME / FACILITY DIRECTORY

OWEN SOUND (COOK FIELD) ON

CCK5

REF	N44 38 05 W80 44 45 10E 10°W (2011) UTC-5(4) Elev 1040' A5000
OPR	Jim Cook 519-379-4964 Reg PPR
PF	B-1 D-2,3,4,5,6
FLT PLN	
FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
RWY DATA	Rwy 09(092°)/27(272°) 2191x80 GRASS
RCR	Ltd hrs. No win maint. Rwy soft in spring.
COMM	
ATF	tfc 123.0 3NM 4100 ASL
PRO	Recommend W dep, rising terrain to the E.
CAUTION	Drainage ditch on either side of centre of rwy.



ONTARIO

AERODROME / FACILITY DIRECTORY

OWEN SOUND / BILLY BISHOP REGIONAL ON — See MEAFORD / MAJOR-GENERAL RICHARD ROHMER