

NEW BRUNSWICK

AERODROME / FACILITY DIRECTORY

FLORENCEVILLE NB

CCR3

REF	N46 25 34 W67 37 41 0.7SW 18°W (2013) UTC-4(3) Elev 508' A5002 A5003 LO8 HI6 RCAP
OPR	McCain Foods Ltd 506-392-3800 Reg PPR
PF	A-1 C-2,3,4,5,6
CUST	AOE/15 13-21Z† Mon-Fri exc hols 888-226-7277
FLT PLN	
FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
ACC	(IFR only) Moncton 506-867-7177 or 866-480-8200.
RWY DATA	Rwy 18(176°)/36(356°) 5414x100 asphalt Rwy 36 up 0.96%
RCR	Opr 13-21Z† O/T 506-612-0686 Ltd win maint
LIGHTING	18-(LO) V2 2.75°, 36-AS(LO) V2 2.75° ARCAL-123.0 for 15 min period, key mic 5 times; 3 times for low ints.
COMM	
ATF	tfc 122.8 5NM 3500 ASL
PRO	Activate ARCAL dur day & night ops.
CAUTION	Hangar complex E of Rwy 18 thld within 100' of rwy edge.

