


ONTARIO

AERODROME / FACILITY DIRECTORY

ROCKTON ON

CPT3

REF	N43 19 20 W80 10 35 1.5W 10°W UTC-5(4) Elev 846' VTA A5000
OPR	SOSA Gliding Club 519-740-9328 Reg PPR
PF	C-1,2 D-3,4,5,6
FLT PLN	FIC London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
RWY DATA	Rwy 03/21 2445x200 GRASS Thld 03 displ 550'. Thld 21 displ 600'. Rwy 18/36 2600x200 GRASS Thld 18 displ 650'. Thld 36 displ 250'. Rwy 10/28 1730x200 GRASS Thld 10 displ 300'. Thld 28 displ 400'. RCR Opr No win maint. Rwy soft when wet & in spring.
COMM	ATF UNICOM ltd hrs O/T tfc 122.725 5NM 3800 ASL
PRO	Rgt hand circuits for powered aircraft (CAR 602.96). Gliders std left hand circuits. Glider activity. Significant glider activity Mar-Dec.
CAUTION	Trees 60 AGL aprx 225' fr Thld 21. Extv wind shear on apch Rwy 21 with wind fr 210°. Wind blanking fr hg left side rwy on tkof Rwy 36. Active winch launched gliders, cable to 2800 ASL within 1NM.



ONTARIO

AERODROME / FACILITY DIRECTORY

ROCKY MOUNTAIN HOUSE (GEN HOSP) AB (Heli) — See ROCKY MOUNTAIN HOUSE
(HEALTH CTR)