

ONTARIO

AERODROME / FACILITY DIRECTORY

PELEE ISLAND ON

CYPT

REF	N41 46 39 W82 40 41 Adj S 8°W (2013) UTC-5(4) Elev 572' A5000 LO6 T2 CAP
OPR	Township of Pelee 519-322-8524, 519-792-9468 Reg
PF	A-1 C-2,3,4,5
CUST	AOE/15 13-01Z± Mon-Thu & Sat, 13-04Z± Fri & Sun May 1-Sep 15; 14-22Z± dly Sep 16-Apr 30 888-226-7277 PN
FLT PLN	IFR dep to Windsor (CYQG) or Detroit TCA-see PRO
FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
RWY DATA	Rwy 10(097°)/28(277°) 3303x75 asphalt AGN II Rwy 01(007°)/19(187°) 2113x15 gravel Thld 01 displ 300'. Avbl day VFR only. PPR Opr 519-724-2931/2671.
RCR	Opr 14-22Z± Ltd win maint Rwy 10/28. No win maint Rwy 01/19.
LIGHTING	10-AS(TE ME) AP, 28-AS(TE ME) AP ARCAL-123.2 type K, to turn RILS off 3 keys.
COMM	
ATF	tfc 123.2 5NM 3600 ASL
ARR	Cleveland Apch 126.35 360.0
DEP	Cleveland Apch 126.35 360.0
PRO	IFR dep for Windsor (CYQG), Detroit city or Detroit airspace call Cleveland Approach Control 216-898-2040 for dep clnc. Pilots are requested to avoid flight below 2000 ASL when flying over the Jack Miner Bird Sanctuary (Kingsville, On N42 04 00 W82 45 00) & over Point Pelee National Park.

