

BRITISH COLUMBIA

AERODROME/FACILITY DIRECTORY

ATLIN BC

CYSQ

REF	N59 34 35 W133 40 17 1NE 18°E (2025) UTC-8(7) Elev 2351' A5021 A5099 LO5 RCAP
OPR	Atlin District Apt Association 250-517-8061, 250-306-4828 Reg
PF	B-1 C-2,3,4,5
CUST	AOE/15 888-226-7277 17-05Z†
FLT PLN	
FIC	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)
WX	WxCam
SERVICES	
FUEL	100LL, JA
S	5,6
RWY DATA	Rwy 01(013°)/19(193°) 3949x75 gravel Rwy 19 down 0.68%
RCR	Opr 16-05Z† Ltd win maint.
LIGHTING	01-AS(TE ME) P1 4.5°, 19-(TE ME) P1 4.5° ARCAL-123.2 type K exc RILS on hi setting only. Retro-reflective markers on twy & aprons only.
COMM	
RCO	Whitehorse rdo 123.55 (FISE) 126.7 (bcst)
ATF	tfc 123.2 5NM 5300 ASL
PRO	Rgt hand circuits Rwy 01 (CAR 602.96). Night circuit: Alt 3400 ASL. Not auth unless both hazard bcns & PAPI opr. All turns to be completed within perimeter of hazard bcns. See VTPC.
CAUTION	Only pilots familiar with lcl terrain should use this apt dur hrs of darkness. Gnd rises sharply fr shoulder edge along E side of rwy. Loose GRVL. Deep snow and hi snow banks in win.

