


ONTARIO

AERODROME / FACILITY DIRECTORY

SANDY LAKE ON

CZSJ

REF	N53 03 51 W93 20 40 Adj NE 1°W (2021) UTC-6(5) Elev 951' A5017 LO3 CAP		
OPR	Govt of Ontario - MTO 807-774-4521 14-23Z± Mon-Fri exc hols Cert		
PF	C-1,4		
FLT PLN	Pilots to open/close VFR flt plan with London rdo, FISE or by phone		
FIC	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)		
WX	METAR AUTO H24 (see COMM) WxCam TAF 11-23Z±, issue times: 1040, 1740Z (DT 0940, 1640Z)		
RWY DATA	Rwy 11(114°)/29(294°) 3507x100 GRVL Rwy 11 up 0.40% Rwy 29 up 1.03%		
RWY CERT	Rwy 11/29 AGN IIIA		
APRON	Apron I - ATB, Apron II - Cargo		
RCR	Aprt Foreperson 807-633-1338 or Opr 14-23Z± Mon-Fri exc hols. Rwy strength & cond subject to seasonal & climatic var.		
LIGHTING	11-AS(TE ME) AP, 29-AS(TE ME) AP ARCAL-122.8 type K		
COMM	ATF tfc 122.8 5NM 4000 ASL AWOS 124.825		
NAV	NDB ZSJ 258 (M) N53 04 06 W93 20 40 Unmonitored		
CAUTION	Rdo transmission blind spot lctd between Apron I and Apron II. Transmission made on the rwy received normally by acft in flt. Lgtd twr 1105 ASL (150 AGL) aprx 0.24NM N of A/D. Twr aprx 1080 ASL aprx 0.54NM S of A/D. Lgtd twr 1135 ASL (150 AGL) aprx 0.97NM SE of A/D. Unlgtd P-line up to aprx 1098 ASL (129 AGL) from 4.5NM WNW of Thld 11 to 0.3NM SSW of Thld 11.		