

CANADA FLIGHT SUPPLEMENT / GPH 205

Effective 0901Z 12 August 2021 to 0901Z 7 October 2021

AERODROME/FACILITY DIRECTORY B1107

TORONTO / DOWNSVIEW ON

CYZD

REF	N43 44 34 W79 27 56 Adj N 11°W UTC-5(4) Elev 652' VTA A5000 LO6 HI5 T2 CAP	
OPR	Bombardier Ops 416-375-3933 Cert PPR	
PF	C-1,2,3,4,5,6	
CUST	AOE/CAN	
FLT PLN	<p>FIG London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)</p> <p>ACC Toronto 905-676-4590/4591/4592 or 888-217-1241</p> <p>WX AUTO (see COMM)</p> <p>DUAT Bombardier Ops 416-375-3933</p>	
SERVICES	24 hr PPR all acft.	
FUEL	JA-1	
S	1	
JASU	10/15	
PVT ADV	Bombardier Ops (VE9JS) 130.075	
RWY DATA	Rwy 15(153°)/33(333°) 7003x200 ASPH	
RWY CERT	Rwy 15 RVR 1200(1/4sm)/ Rwy 33 RVR 1200(1/4sm) AGN IIIB	
RCR	Opr PLR/PCN.	
LIGHTING	15-AS(TE ME) P2, 33-AS(TE ME) P2	
COMM	<p>MF UNICOM 13-23Z‡ Mon-Fri O/T tfc 126.2 3NM 1700 ASL (CAR 602.98)</p> <p>ARR Toronto 133.4</p> <p>DEP Toronto 133.4</p> <p>AUTO 122.975</p>	
PRO	Rgt hand circuits Rwy 33 (CAR 602.96). Tfc patterns. Fixed wing 1500 ASL. Pilots are requested to maintain 2000 ASL or above over Metro Toronto Zoo (N43 49 05 W79 11 15). Prior to taxi, ctc Downsview UNICOM for ATC clearances & aprt info.	
CAUTION	Extv bird activity on A/D.	

