


## CANADA FLIGHT SUPPLEMENT / GPH 205

Effective 0901Z 12 August 2021 to 0901Z 7 October 2021

### B1076 AERODROME/FACILITY DIRECTORY

**TERRACE BC**

**CYXT**



<b>REF</b>	N54 28 07 W128 34 42 3S 19°E (2014) UTC-8(7) Elev 713' A5013 LO1 HI3 CAP
<b>OPR</b>	Terrace-Kitimat Aprt Society 250-635-2659 Cert
<b>PF</b>	A-1,2,3,6,7 C-4,5
<b>FLT PLN</b>	<p><b>FIG</b> Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada &amp; USA)</p> <p><b>WX</b> METAR H24. TAF H24, issue times: 01, 07, 13, 19Z.</p>
<b>SERVICES</b>	<p><b>FUEL</b> 100LL, JA-1 (FSII avbl) 16-01Z±, 250-638-1564, O/T call out chg may be levied.</p> <p><b>OIL</b> All</p> <p><b>S</b> 5 May 01-Oct 31</p> <p><b>ARFF</b> DESIGNATED CAT 6 for sked acft 20 seats and abv, other acft 2hr PN 250-615-7636. Call out chg.</p> <p><b>PVT ADV</b> Executive Flight Centre 250-638-1564 Fax 250-638-1589</p> <p><b>MILCON</b> Associated Energy Group 250-638-1564</p>
<b>RWY DATA</b>	Rwy 15(153°)/33(333°) 7497x148 ASPH Rwy 03(033°)/21(213°) 5371x148 ASPH Rwy 03 up 0.69%
<b>RWY CERT</b>	Rwy 15 RVR 1200(1/4sm) Day only/Rwy 33 RVR 1200(1/4sm) Day only AGN IV Rwy 03/21 AGN IIIA
<b>TWY</b>	Twy B uncontrolled first 2000' fr apron
<b>APRON</b>	Tran acft must park in SE corner of Apron. Itinerant parking with tiedowns on grass May to Oct. N side main apron stands 1-3 are rstd to sked tfc only. All stands PPR. Itinerant pilot/pax access via pilot access door on E end of tml bldg. No access/egress via tml bldg facility is permitted. Exceptions require prior approval of aprt opr. Corporate itinerant prkg ctc Executive Flight Centre.
<b>RCR</b>	Opr Win maint 1330-0800Z± Mon-Fri, 1330-0430Z± Sat, 1730-0800Z± Sun O/T 2 hrs PN 250-615-7636, cost recovery. Rwy 03/21 no win maint. Ltd hrs CRFI, PLR/PCN

**CANADA FLIGHT SUPPLEMENT / GPH 205**

Effective 0901Z 12 August 2021 to 0901Z 7 October 2021

**AERODROME/FACILITY DIRECTORY B1077**

**TERRACE BC (Cont'd)**

**CYXT**

<b>LIGHTING</b>	15-AO(TE HI) P2, 33-AN(TE HI) P2 3.5° ARCAL-122.0 type K PAPI limitation/restriction. PAPI Rwy 33 to be used only within 2NM of thld.
<b>COMM</b>	
<b>RADIO</b>	122.0 (E) (emerg only 250-635-2110)
<b>RCO</b>	Pacific rdo 123.375(FISE) 126.7 (bcst)
<b>MF</b>	rdo 122.0 5NM 3700 ASL (CAR 602.98)
<b>PAL</b>	Vancouver Ctr 128.4 269.1
<b>NAV</b>	
<b>NDB</b>	XT 332 (M) N54 22 27 W128 35 04 KITIMAT ZKI 203 (M) N54 03 15 W128 40 12
<b>DME</b>	IXT 110.1 Ch 38 N54 27 39 W128 35 16
<b>ILS</b>	IXT 110.1 (Rwy 33) LOC reliable only within 10° either side of centerline.
<b>PRO</b>	Rgt hand circuits Rwy 33 (CAR 602.96). Ngt circuit pro, see VTPC.
<b>CAUTION</b>	Ngt ops not recommended unless all hazard bcns are oprg. Recommend that only pilots familiar with the local area use the aprt dur the hrs of darkness. Hi terrain reduces operational length of Rwy 33 PAPI.

**TERRACE FSS – RCO**

**Sandspit** 122.3 (RAAS) 296.2 (RAAS) (N53 15 W131 48)

**TESLIN YT**

**CYZW**

<b>REF</b>	N60 10 22 W132 44 38 Adj NW 21°E (2014) UTC-7 Elev 2303' A5028 A5099 LO5 HI2 CAP RCAP	
<b>OPR</b>	Govt of Yukon 867-634-2046 or 867-993-2909 Reg	
<b>PF</b>	A-1 C-2,4,5	
<b>FLT PLN</b>		
<b>FIG</b>	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)	
<b>CARS</b>	867-390-2525 Ltd hrs (see COMM) Fax 867-390-2528	
<b>WX</b>	METAR dur CARS hrs (see COMM) O/T LWIS TAF 18-24Z Oct 1-May 31; 15-01Z Jun 1-Sep 30; issue times: 18Z Oct 1-May 31; 15, 18Z Jun 1-Sep 30.	
<b>SERVICES</b>	Fuel stor by permit only ctc opr 4,5,6	
<b>RWY DATA</b>	Rwy 09(086°)/27(266°) 5028x100 GRVL Rwy 27 down 0.50%	
<b>RWY CERT</b>	Rwy 09/27 AGN IIIA	
<b>RCR</b>	CARS, dur CARS hrs ops (see COMM), ltd maint.	
<b>LIGHTING</b>	09-(TE LO) V1, 27-(TE LO) V1 4° ARCAL-122.1 type J	
<b>COMM</b>		
<b>MF</b>	aprt rdo ltd hrs O/T tfc 122.1 5NM 5400 ASL (CAR 602.98)	
<b>APRT RDO</b>	122.1 (V) 13-01Z Jun 1-Sep 30; 16-24Z Oct 1-May 31	
<b>PRO</b>	Rgt hand circuits Rwy 09 (CAR 602.96).	
<b>CAUTION</b>	Rwy sfc soft in spring & when wet. Frost heaves may occur in area 600' fr thld Rwy 27.	