

## QUEBEC

## AERODROME / FACILITY DIRECTORY

## TASIUJAJQ QC

CYTQ

<b>REF</b>	N58 40 04 W69 57 21 1.5SW 22°W (2020) UTC-5(4) Elev 121' A5027 LO5 CAP	
<b>OPR</b>	Administration Régionale Kativik 819-964-2968 14-22Z‡ Mon-Fri O/T 819-964-3434 Ext 154 Fax 819-964-2462 Cert	
<b>PF</b>	A-1 C-2,4,5,7	
<b>FLT PLN</b>		
<b>FIC</b>	(bil) Québec 866-GOMÉTÉO or 866-WXBRIEF (Toll free within Canada) or 866-541-4105 (Toll free within Canada & USA)	
<b>ACC</b>	Montréal 800-633-1353	
<b>CARS</b>	819-633-1530 ltd hrs (see COMM)	
<b>WX</b>	METAR dur CARS hrs (see COMM) O/T LWIS TAF 15-22Z‡, issue times: 15, 20Z (DT 14Z).	
<b>RWY DATA</b>	Rwy 05(053°)/23(233°) 3519x100 GRVL Rwy 05 down 0.7% first 2390'	
<b>RWY CERT</b>	Rwy 05/23 AGN IIIA	
<b>RCR</b>	Opr 13-21Z‡ Mon-Fri exc hols May 1-Sep 30; Win maint 13-21Z‡ exc hols, O/T 3 hr PN Oct 1-Apr 30. CRFI, PCN.	
<b>LIGHTING</b>	05-AS(TE ME), 23-AS(TE ME) ARCAL-122.1 type K	
<b>COMM</b>		
<b>MF</b>	aprt rdo (English only) ltd hrs O/T tfc 122.1 15NM joined to Aupaluk MF circle by a corridor equal to the width of their diameter 3500 ASL (CAR 602.98), see Aupaluk/Kangirsuk/Tasiujaq VTPC.	
<b>APRT RDO</b>	122.1 (V) 1230-2230Z‡	
<b>CAUTION</b>	Unlgt'd P-line 40 AGL (161 ASL) 500' NE Thld 23. Presence of permafrost ventilation pipes within the rwy strip. A/D status unkn aprx 7NM SW with possibility of acft and heli tfc Jun-Oct.	