

## BRITISH COLUMBIA

## AERODROME / FACILITY DIRECTORY

## CHETWYND BC

CYCQ

<b>REF</b>	N55 41 14 W121 37 36 Adj S 19°E (2013) UTC-7 Elev 1999' A5014 LO1 CAP	
<b>OPR</b>	District of Chetwynd 250-401-4100 Reg	
<b>PF</b>	A-1 C-2,3,4,5,6	
<b>FLT PLN</b>	<p><b>FIG</b> Edmonton 866-WXBRIEF (Toll free within Canada) or 866-541-4102 (Toll free within Canada &amp; USA)</p> <p><b>WX</b> METAR 13-01Z fr second Sun in Mar. 14-24Z fr first Sun in Nov. O/T LWIS. AUTO (see COMM) Webcam</p>	
<b>SERVICES</b>	Tml access code 0101*	
<b>FUEL</b>	JA (Heli only) Ridge Rotors 250-788-4158 JA-1 Executive Flight Center 250-785-6174 (main) or 250-793-1734 Smart Card/VISA/MASTERCARD Access 4,5,6	
<b>S</b>		
<b>RWY DATA</b>	Rwy 05(054°)/23(234°) 4481x100 ASPH AGN IIIA	
<b>RCR</b>	Opr Ltd win maint	
<b>LIGHTING</b>	05-AS(TE ME), 23-AS(TE ME) V2 ARCAL-126.7 type K, exc RILS on hi setting only. Ngt ops are not recommended unless all 3 hazard beacons are oprg.	
<b>COMM</b>		
<b>ATF</b>	tfc 123.2 5NM 5000 ASL	
<b>AUTO</b>	122.55	
<b>PRO</b>	Rgt hand circuits Rwy 05 (CAR 602.96). Ngt circuits 3700 ASL. Ngt circuit pro depicted on VTPC. All IFR departures call Edmonton ACC at 888-358-7526 for IFR clnc prior to dep.	
<b>CAUTION</b>	Only pilots familiar with lcl terrain should use this aprt dur hrs of darkness. Moderate to severe turbulence & wind shear may be encountered on apch. Wild animals may stray on to rwy. Lgtg group of wind turbines to 4040 ASL (674 AGL) aprx 9.6NM SSE of A/D, 3932 ASL (674 AGL) aprx 8.7NM SSE of A/D.	