

## MANITOBA

## AERODROME / FACILITY DIRECTORY

## THOMPSON MB

CYTH

<b>REF</b>	N55 48 17 W97 51 45 3N 3°E (2014) UTC-6(5) Elev 735' A5016 LO3 HI4 CAP	
<b>OPR</b>	Thompson Regional Aprt Authority APM 204-677-0724 O/T 204-679-0295 12-02Z† Sun-Fri, 14-23Z† Sat exc hols Cert Ldg fees	
<b>PF</b>	A-1,2,3,6 C-4,5	
<b>FLT PLN</b>	Pilots to open/close VFR flt plan with Edmonton rdo, FISE or by phone.	
<b>FIC</b>	Edmonton 866-WXBRIEF (Toll free within Canada) or 866-541-4102 (Toll free within Canada & USA)	
<b>WX</b>	METAR H24. TAF H24, issue times: 01, 07, 13, 19Z.	
<b>SERVICES</b>	Call out chg may be levied for one or more svcs	
<b>FUEL</b>	100LL, JA-1, JB	
<b>OIL</b>	All	
<b>S</b>	1,2,3,4,5,6 O/T 1 hr PN for all call outs	
<b>SUP FL</b>	D & A-ice	
<b>PVT ADV</b>	Shell 122.95 call sign VXH74 204-677-2337, 1330-0030Z† Mon-Fri, 16-24Z† Sat & Sun O/T 204-679-1311	
<b>RWY DATA</b>	Rwy 06(058°)/24(238°) 5800x150 ASPH Rwy 15(148°)/33(328°) 5079x100 GRVL Rwy 33 up 0.67%	
<b>RWY CERT</b>	Rwy 06/24 AGN IV Rwy 15/33 AGN IIIB	
<b>TWY CERT</b>	Twy B AGN IIIB	
<b>APRON</b>	Apron I: General Avn acft to park in designated locations on NW edge, W of twy A (no exceptions). Medevac and commercial charter acft to park on E portion, adj to aprt maint shop. De-icing, runups and eqpt staging to take place on E edge. Prkg fees applicable after 2 hrs. Acft parked in non-designated areas will be subject to extra fees.	
<b>RCR</b>	OPR 204-677-0726 Mon-Fri O/T 204-679-0295 CRFI, Rwys maint 12-02Z† Sun-Fri, 14-23Z† Sat exc hols. O/T 1 hr PN for AMSCR and CRFI PCN. Call out chg.	
<b>LIGHTING</b>	06-AN(TE HI) P2, 24-AO(TE HI) P2, 15-(TE ME), 33-(TE ME)	
<b>COMM</b>		
<b>RADIO</b>	122.5 (V) (emerg only 204-677-6979)	
<b>RCO</b>	Edmonton rdo 123.55 (FISE) 126.7 (bcst)	
<b>ATIS</b>	127.65	
<b>MF</b>	rdo 122.5 5NM 4000 ASL (CAR 602.98)	
<b>PAL</b>	Winnipeg Ctr 133.15	
<b>NAV</b>		
<b>VOR/DME</b>	YTH 112.9 Ch 76 N55 48 40 W97 49 31 (791')	
<b>ILS</b>	ITH 110.3 (Rwy 06) RVR	
<b>PRO</b>	Rgt hand circuits Rwys 15 & 24 (CAR 602.96).	
<b>CAUTION</b>	Extv frost heaves on Apron I, on Rwy 06/24 at Twy A and Rwy 15/33 intxn & on Rwy 15/33 570 ft to 710 ft N of rwy intxns. Rwy 15/33 & Twy B not recommended for jet acft due to loose gravel.	