

BRITISH COLUMBIA

AERODROME / FACILITY DIRECTORY

PORT HARDY BC

CYZT

REF	N50 40 50 W127 22 00 5.2SE 18°E (2014) UTC-8(7) Elev 71' A5004 LO2 HI3 CAP	
OPR	TC 250-949-6424 O/T Duty 250-902-8281 Fax 250-949-9013 16-24Z‡ Mon-Fri, Sat-Sun and hols O/R. Call out chg may apply, ctc opr. Cert Ldg fees (jet and turboprop acct only) Tml fees	
PF	A-1,2,3,6 C-5 D-4 ATB 1530-0030Z‡ Mon-Fri, Sat-Sun & hols O/R	
CUST	AOE/15 888-226-7277 16-08Z‡	
FLT PLN		
FIC	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)	
WX	METAR H24. TAF H24, issue times: 01, 07, 13, 19Z.	
SERVICE		
FUEL	100LL, JA-1 (FSII avbl), HPR Wilderness Seaplanes (World Fuel) 250-949-1037 16-01Z‡ Mon-Fri, 17-24‡ Sat-Sun exc hols, O/T call out chg apply.	
OIL	All	
S	1,2,4,5,6	
PVT ADV	Wilderness Seaplanes 131.05 250-949-1037 or 250-949-6353	
MIL CON	Wilderness Seaplanes Ltd 250-949-5153	
RWY DATA	Rwy 11(113°)/29(293°) 4999x150 grooved ASPH Rwy 08(076°)/26(256°) 4000x150 ASPH Rwy 26 up 0.98% Rwy 16(162°)/34(342°) 3984x150 ASPH Rwy 16 up 0.75% Thld 34 displ 1491'	
RWY CERT	Rwy 29 RVR 1200(1/4sm) Rwy 11/29 AGN IIIA Rwy 08/26 AGN I Rwy 16/34 AGN I	
TWY CERT	Twy: A, B AGN II	
TWY	No vehicle control	
APRON	Prkg fees Pvt pilot access ATB/airside via pilot gate, entry code attached. Apron III: Prkg only for heli on skids with max gr wt 13,000 lbs	
RCR	Opr CRFI, Win maint 1430-2300Z‡ Mon-Fri exc hols O/T PN, call out chgs apply. No win maint Rwy 16/34. Rwy 16/34 rstd to acct gr wt of 12,500 lbs or less. PCN	
LIGHTING	08-(TE ME), 26-(TE ME) P2, 11-AO(TE ME), 29-AO(TE ME) P2	
COMM		
RADIO	Hardy 122.2 PTC avbl (E) (emerg only 250-949-6331)	
RCO	Pacific rdo 123.375 (FISE) 126.7 (bcst)	
MF	Hardy rdo 122.2 5NM 3100 ASL excluding class G ATF (CAR 602.98). Refer to Port Hardy VTPC.	
PAL	Vancouver Ctr 132.2 266.3	
NAV		
VOR/DME	YZT 112.0 Ch 57 N50 41 04 W127 21 57 (67')	
ILS	IZT 109.5 (Rwy 11)	

BRITISH COLUMBIA

AERODROME / FACILITY DIRECTORY

PORT HARDY BC (Cont'd)

CYZT

PRO	Rgt hand circuits Rwys 26 & 29 (CAR 602.96). Reduced Visibility Operations Plan (RVOP): Rwy 08/26, Rwy 16/34 and Twy A not available for acft taxi when vis below RVR 2600 (1/2sm) (CAR 602.96). Pilots preparing to depart the ramp in vis less than RVR 2600 (1/2sm) must ensure that no other acft are on the maneuvering areas (CAR 602.96).
CAUTION	Extv eagle activity in the vic of Thlds 26 & 29. Radiosonde balloon launches with an ascent rate of 1000 ft/min daily between the hours of 1115-1345Z and 2315-0145Z.