

REF	N51 46 29 W114 40 51 2SW 15°E (2012) UTC-7(6) Elev 3663' A5005 LO2 T1 CAP	
OPR	KS2 Management Ltd. 825-994-4815, 403-829-8105 Reg	
PF	A-1 C-2,3,4,5 D-6	
FLT PLN		
FIC	Edmonton 866-WXBRIEF (Toll free within Canada) or 866-541-4102 (Toll free within Canada & USA)	
ACC	Edmonton IFR 888-358-7526	
SERVICES		
FUEL	100LL, JA	
S	2,4,5,6	
RWY DATA	Rwy 15(147°)/33(327°) 4346x75 ASPH AGN IIIA Rwy 06(057°)/24(237°) 2439x75 grass Rwy 24 up 0.53%	
RCR	Qpr Ltd win maint PLR	
LIGHTING	15-(TE ME), 33-(TE ME) ARCAL-123.2 type K	
COMM		
ATF	tfc 123.2 5NM 6700 ASL	
NAV		
NDB	9G 405 (M) N51 46 48 W114 41 00 Pvt Unmonitored	
CAUTION	tfc at Sundre/Goodwins Farm, 1.5NM SE. Gravel pit N of Thld 15. Road adj to Thld 06.	