

BRITISH COLUMBIA

AERODROME / FACILITY DIRECTORY

PORT HARDY BC

CYZT

REF	N50 40 50 W127 22 00 5.2SE 18°E (2014) UTC-8(7) Elev 71' A5004 LO2 HI3 CAP	
OPR	TC 250-949-6424 O/T Duty 250-902-8281 Fax 250-949-9013 1430-2230Z† Mon-Fri, Sat-Sun and hols O/R. Call out chg may apply, ctc opr. Cert Ldg fees (jet and turboprop acft only) Tml fees	
PF	A-1,2,3,6 C-5 D-4 ATB 1530-0030Z† Mon-Fri, Sat-Sun & hols O/R	
CUST	AOE/15 888-226-7277 16-08Z†	
FLT PLN	FIC Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA) WX METAR H24. TAF H24, issue times: 01, 07, 13, 19Z.	
SERVICE	FUEL 100LL, JA-1 (FSII avbl), HPR Wilderness Seaplanes (World Fuel) 250-949-1037 16-01Z† Mon-Fri, 17-24† Sat-Sun exc hols, O/T call out chg apply. OIL All S 1,2,4,5,6 PVT ADV Wilderness Seaplanes 131.05 250-949-1037 or 250-949-6353 MIL CON Pacific Coastal Airlines (World Fuel Services) 250-949-5153	
RWY DATA	Rwy 11(113°)/29(293°) 4999x150 grooved ASPH Rwy 08(076°)/26(256°) 4000x150 ASPH Rwy 26 up 0.98% Rwy 16(162°)/34(342°) 3984x150 ASPH Rwy 16 up 0.75% Thld 34 displ 1491' RWY CERT Rwy 29 RVR 1200(1/4sm) Rwy 11/29 AGN IIIA Rwy 08/26 AGN I Rwy 16/34 AGN I TWY CERT Twy: A, B AGN II TWY No vehicle control APRON Prkg fees Pvt pilot access ATB/airside via pilot gate, entry code attached. RCR Opr CRFI, Win maint 1430-2300Z† Mon-Fri exc hols O/T PN, call out chgs apply. No win maint Rwy 16/34. Rwy 16/34 rstd to acft gr wt of 12,500 lbs or less. PLR/PCN.	
LIGHTING	08-(TE ME), 26-(TE ME) P2, 11-AO(TE ME), 29-AO(TE ME) P2	
COMM	RADIO Hardy 122.2 PTC avbl (E) (emerg only 250-949-6331) RCO Pacific rdo 123.375 (FISE) 126.7 (bcst) MF Hardy rdo 122.2 5NM 3100 ASL excluding class G ATF (CAR 602.98). Refer to Port Hardy VTPC. PAL Vancouver Ctr 132.2 266.3	
NAV	VOR/DME YZT 112.0 Ch 57 N50 41 04 W127 21 57 (67') DME IZT 109.5 Ch 32 N50 40 34 W127 21 09 (21') ILS IZT 109.5 (Rwy 11) LOC reliable only within 10° either side of centreline.	

PORT HARDY BC (Cont'd)

CYZT

PRO	Rgt hand circuits Rwys 26 & 29 (CAR 602.96). Reduced Visibility Operations Plan (RVOP): Rwy 08/26, Rwy 16/34 and Twy A not available for acft taxi when vis below RVR 2600 (1/2sm) (CAR 602.96). Pilots preparing to depart the ramp in vis less than RVR 2600 (1/2sm) must ensure that no other acft are on the maneuvering areas (CAR 602.96).
CAUTION	Extv eagle activity in the vic of Thlds 26 & 29. Radiosonde balloon launches with an ascent rate of 1000 ft/min daily between the hours of 1115-1345Z and 2315-0145Z.