

ONTARIO

AERODROME / FACILITY DIRECTORY

**HALIBURTON / STANHOPE MUNI ON**

**CND4**

|                 |  |  |
|-----------------|--|--|
| <b>REF</b>      | N45 06 39 W78 38 24 6.9NW 12°W<br>UTC-5(4) Elev 1066' A5000                                  |  |
| <b>OPR</b>      | Township of Algonquin Highlands<br>705-754-2611/489-2342 Reg                                 |  |
| <b>PF</b>       | B-1 C-2,3,4,5,6  |  |
| <b>FLT PLN</b>  |  |  |
| <b>FIC</b>      | London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA) |  |
| <b>SERVICES</b> | Dur oprg hrs. Call out chg for one or more svcs may be levied after hrs.                     |  |
| <b>FUEL</b>     | 100LL, JA-1 (FSII avbl) Cardlock on Apron  |  |
| <b>OIL</b>      | All Aeroshell  |  |
| <b>S</b>        | 2,3,4,5,6  |  |
| <b>RWY DATA</b> | Rwy 08(084°)/26(264°) 2500x60 ASPH   |  |
| <b>RCR</b>      | Opr 14-21Z† Thu-Mon Ltd win maint  |  |
| <b>LIGHTING</b> | 08(TE LO), 26-AS(TE LO) ARCAL-123.2 type J (all A/D lgt including rotating beacon)           |  |
| <b>COMM</b>     |  |  |
| <b>ATF</b>      | UNICOM ltd hrs O/T tfc 123.2 5NM 4100 ASL  |  |
| <b>PRO</b>      | Municipal policy restricts ops dur period 04-12Z†, PPR Opr.                                  |  |
| <b>CAUTION</b>  | Northerly winds may cause windshear dur apch/dep Rwy 26. Wildlife in vic of rwy.             |  |