

ONTARIO

AERODROME / FACILITY DIRECTORY

EARLTON (TIMISKAMING REGIONAL) ON

CYXR

REF	N47 41 42 W79 50 56 1SW 12°W UTC-5(4) Elev 800' A5001 LO4 LO7 HI4 HI5 CAP	
OPR	Earlton-Timiskaming Regional Airport Authority 705-563-2215 Cert 1200-2030Z± Mon-Fri exc hols	
PF	B-1 C-2,4, D-3,5,6	
FLT PLN	<p>FIC London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)</p> <p>WX METAR AUTO H24 (see COMM) TAF 13-01Z±, issue times: 13, 18Z (DT 12, 18Z). WxCam</p>	
SERVICES	<p>FUEL 100LL, JA-1 1200-2030Z± Mon-Fri exc hols, O/T Cardlock (VISA/Mastercard)</p> <p>OIL 100, 15W50</p>	
RWY DATA	<p>Rwy 08(075°)/26(255°) 5998x150 asphalt</p> <p>Rwy 16(160°)/34(340°) 3019x150 grvl Rwy 34 up 0.86%</p>	
RWY CERT	<p>Rwy 08/26 AGN IIIA</p> <p>Rwy 16/34 AGN I</p>	
RCR	<p>London FIC AMSCR/CRFI 1100-2030Z± Mon-Fri exc hol Nov 7-Apr 17 O/T 3hr PN call out charge may be levied ctc opr. PLR/PCN Rwy 16/34 No win maint Soft in spring & fall</p>	
LIGHTING	<p>08-AD(TE ME) V2, 16-(TE ME) 26-AD AS(TE ME) V2, 34-(TE ME) ARCAL-122.0 type K. RILS activated by ARCAL on high ints setting only. Rwy16/34 not avbl Nov 7-Apr 16.</p>	
COMM	<p>RCO London rdo 123.375 (FISE)</p> <p>MF tfc 122.0 5NM 3800 ASL (CAR 602.98)</p> <p>AWOS 128.6</p>	
PRO	<p>Rgt hand circuits Rwy 08 (CAR 602.96).</p>	