


DRAYTON VALLEY INDUSTRIAL AB

CER3

REF	N53 15 48 W114 57 31 2.5NE 16°E (2012) UTC-7(6) Elev 2774' A5014 A5015 LO2 CAP	
OPR	PRAA 780-514-8013 or 866-719-9059 Reg	
PF	B-1 C-2,3,4,5,6	
FLT PLN		
FIC	Edmonton 866-WXBRIEF (Toll free within Canada) or 866-541-4102 (Toll free within Canada & USA)	
ACC	Edmonton IFR 888-358-7526	
SERVICES		
FUEL	100LL self serve Pembina Regional Aerodrome Association 780-514-8013	
S	1,2,4,5,6	
RWY DATA	Rwy 14(144°)/32(324°) 5065x75 ASPH Rwy 14 down 0.39% Thld 14 displ 1492' AGN II	
RCR	Opr Ltd maint	
LIGHTING	14-(TE ME) P1, 32-(TE ME) P1 ARCAL-122.8 type K	
COMM		
ATF	UNICOM ltd hrs O/T tfc 122.8 5NM 5800 ASL	
CAUTION	Acft on opposite ends of rwy may not be visible to each other. Wild animals may stray onto rwy. RPAS activity 3.3 NM NNW of A/D max 400 AGL. Grass tkof/lbg area 2130'x50' adj E Rwy 14/32, SE of Twy A. May be soft when wet. No win maint.	