

AERODROME/FACILITY DIRECTORY

CYQZ

REF	N53 01 34 W122 30 37 2N 17°E (2020) UTC-8(7) Elev 1788' A5014 LO2 HI3 CAP	
OPR	City 250-992-2208 15-01Z† Mon-Fri, 17-01Z† Sun exc hols onsite coverage for sked commercial flts only. O/T 2 hr PN Cert	
PF	A-1,6 C-2,3,4,5	
FLT PLN	FIC Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA) WX METAR AUTO H24 (See COMM) TAF 12-06Z, issue times: 12, 19, 01Z. WxCam	
SERVICES	FUEL 100LL, JA-1 (FSII avbl), SP 250-992-2208 (Self-serve, Visa, Mastercard & pvt accounts only). Heli refueling at heli touchdown pad NW of apron. S 2,4,5,6	
RWY DATA	Rwy 13(133°)/31(313°) 5501x150 CONC/ASPH	
RWY CERT	Rwy 13/31 AGN IIIB	
TWY	Twy B pvt use only	
RCR	Opr CRFI, Win maint 14-03Z† Mon-Fri Nov-Mar, 1600-0230Z† Sat-Sun, exc hols O/T 2 hr PN, call out chg may be levied. PCN	
HELI DATA	Parking Pad: 70' x 60' CONC/ASPH Max heli overall length 55.8'	
LIGHTING	13-AO(TE ME) P2, 31-AO(TE ME) P2 ARCAL-122.2 type K	
COMM	RCO Williams Lake rdo 122.2 PTC avbl (RAAS) 14-06Z† MF Williams Lake rdo 14-06Z† O/T tfc 122.2 5NM 4800 ASL (CAR 602.98) AWOS 124.4	
PRO	Rgt hand circuits Rwy 13 (CAR 602.96). Ng't circuit pro see VTPC.	
CAUTION	Adj to and E of both apchs are hills marked by hazard bcns. 100 AGL trees along W side of rwy 500' fr rwy edge. Only pilots familiar with local terrain should use this apt dur hrs of darkness. Ng't ops not recommended unless all 3 hazard bcns are oprg. Extv smoke from pulp mills frequently obscures apch to Rwy 31. Reported winds may not be representative of landing area winds. Extv bird activity Apr-Oct. Possibility of wildlife on rwy.	