

BRITISH COLUMBIA

AERODROME / FACILITY DIRECTORY

QUESNEL BC

CYQZ

REF	N53 01 34 W122 30 37 2N 17°E (2020) UTC-8(7) Elev 1788' A5014 LO2 H13 CAP	
OPR	City 250-992-2208 Cert	
PF	A-1,6 C-2,3,4,5	
FLT PLN		
FIC	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)	
WX	METAR AUTO H24 (See COMM) TAF 12-06Z, issue times: 12, 19, 01Z. WxCam	
SERVICES		
FUEL	100LL, JA-1 (FSII avbl), SP 250-992-2208 (Self-serve, Visa, Mastercard & pvt accounts only). Heli refueling at heli touchdown pad NW of apron.	
S	2,4,5,6	
RWY DATA	Rwy 13(133°)/31(313°) 5501x200 ASPH	
RWY CERT	Rwy 13/31 AGN IIIB	
TWY	Twy B pvt use only	
RCR	Opr CRFI, Win maint Nov 1-Mar 31 - 14-05Z Mon-Wed, 16-05Z Thu, Fri, Sun, 1600-0030Z Sat, exc hols O/T 2 hr PN, call out chg may be levied. PLR/PCN	
HELI DATA	50' x 50' concrete 70' x 70'	
LIGHTING	13-AO(TE ME) P2, 31-AO(TE ME) P2 ARCAL-122.2 type K	
COMM		
RCO	Williams Lake rdo 122.2 (RAAS) 14-06Z±	
MF	Williams Lake rdo 14-06Z± O/T tfc 122.2 5NM 4800 ASL (CAR 602.98)	
AWOS	124.4	
PRO	Rgt hand circuits Rwy 13 (CAR 602.96). Ngt circuit pro see VTPC.	
CAUTION	Adj to and E of both apchs are hills marked by hazard bcns. 100 AGL trees along W side of rwy 500' fr rwy edge. Only pilots familiar with local terrain should use this aprt dur hrs of darkness. Ngt ops not recommended unless all 3 hazard bcns are oprg. Extv smoke from pulp mills frequently obscures apch to Rwy 31. Reported winds may not be representative of landing area winds. Extv bird activity Apr-Oct. Possibility of wildlife on rwy.	