

## ONTARIO

## AERODROME / FACILITY DIRECTORY

## BROCKVILLE REGIONAL TACKABERRY APRT ON

CNL3

<b>REF</b>	N44 38 22 W75 45 01 4.8NW 14°W UTC-5(4) Elev 404' A1905 A5000 A5002 LO6 LO7 T2 CAP	
<b>OPR</b>	Brock Air Services Ltd 613-345-0642 Reg	
<b>PF</b>	B-1 C-2,3,4,5,6	
<b>CUST</b>	AOE/CAN	
<b>FLT PLN</b>	<p><b>FIC</b> London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada &amp; USA)</p> <p><b>WX</b> AUTO at Ogdensburg Intl (KOGS) 315-393-8982 (see COMM). WxCam</p>	
<b>SERVICES</b>	Opr 1130-2030Z† Mon-Sun, after hrs Page 866-340-2076	
<b>FUEL</b>	100LL, JA-1	
<b>S</b>	4,5,6	
<b>RWY DATA</b>	Rwy 04(044°)/22(224°) 4505x90 ASPH Rwy 04 up 1.08% first 845' then down 0.25% AGN II	
<b>RCR</b>	Rwy 16(166°)/34(346°) 2203x75 GRASS Opr Rwy 16/34 no win maint, may be extremely soft dur spring or after hvy rain. PLR	
<b>LIGHTING</b>	04-AS(TE LO) AP, 22-AK(TE LO) AP ARCAL-123.3 type K (All A/D lgt exc MALSF) MALSF-123.5 type K.	
<b>COMM</b>	<p><b>ATF</b> UNICOM ltd hrs O/T tfc 123.0 5NM 3400 ASL</p> <p><b>ARR</b> (bil) Montréal Ctr 134.675</p> <p><b>DEP</b> (bil) Montréal Ctr 134.675</p> <p><b>AUTO</b> 118.525 at Ogdensburg Intl (KOGS)</p>	
<b>CAUTION</b>	Wildlife frequently on rwys. Possible win main eqpt on rwy outside ops hrs. Snow clearing may be conducted after hrs. Acft on opposite ends of Rwy 04/22 may not be visible to each other. Firing range 600 ft beyond Thld 04 and 1200 ft left runway centre line 1230-0400Z† dly. Possible acft overflying on apch into Ogdensburg, NY (KOGS) A/D. Acft approaching KOGS may not be on ATF 123.0. Possible wake turbulence.	