

## ONTARIO

## AERODROME / FACILITY DIRECTORY

## HASTINGS / SWEETWATER FARMS ON

CSW6

<b>REF</b>	N44 20 46 W77 55 40 2.5NE 12°W (2016) UTC-5(4) Elev 675' A5000	
<b>OPR</b>	Bobby Henzie 705-872-7722, 705-696-3193 Reg	
<b>PF</b>	A-1 C-4,5	
<b>FLT PLN</b>		
<b>FIC</b>	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)	
<b>SERVICES</b>		
<b>S</b>	1, 4, 5	
<b>RWY DATA</b>	Rwy 12/30 2800x53 GRASS Rwy 12 slopes down	
<b>RCR</b>	Opr No win maint. Rwy may be soft when wet.	
<b>COMM</b>		
<b>ATF</b>	tfc 123.2 5NM 3800 ASL	
<b>CAUTION</b>	Wildlife on rwy. Bird activity over river.	