

CANADA FLIGHT SUPPLEMENT / GPH 205

Effective 0901Z 17 June 2021 to 0901Z 12 August 2021

AERODROME/FACILITY DIRECTORY B81

BLUE RIVER BC (Cont'd)


CYCP

COMM	
ATF	tfc 123.2 5NM 5200 ASL
CAUTION	Shoulder drops abruptly at edge of pavement. Wildlife in vicinity of rwy. Extv heli activity in the area.

BOBCAYGEON / CHESHER LAKEHURST ON

CLH5

REF	N44 31 32 W78 26 53 4.3ESE 11°W (2017) UTC-5(4) Elev 892' A5000
OPR	Jeff Chesher 705-927-8799 Reg PPR
PF	D-1,2,3,4,5,6
FLT PLN	
FIG	London 866-WXBRIEF (Toll free within Canada) or 866-541-4104 (Toll free within Canada & USA)
RWY DATA	Rwy 17(173°)/35(353°) 1943x98 TURF
RCR	Opr
COMM	
ATF	tfc 122.8 5NM 3900 ASL



BOB QUINN LAKE BC

CBW4

REF	N56 58 00 W130 14 58 20°E (2013) UTC-8(7) Elev 1970' A5021 LO1 RCAP
OPR	Bob Quinn Lake Airport Society 250-249-0079 Reg
PF	C-1
FLT PLN	
FIG	Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA)
WX	WxCam PPR for altimeter availability, etc OPR
RWY DATA	Rwy 15(152°)/33(332°) 4074x100 GRVL
RCR	Opr No win maint
HELI DATA	200' x 100' GRVL
COMM	
DRCO	Pacific rdo 126.7 (FISE)
MF	tfc 123.2 5NM 5000 ASL (CAR 602.98)
PRO	Rgt hand circuits Rwy 15 (CAR 602.96). Fixed wing acft emplane/deplane pax & cargo on apron only
CAUTION	Trees to 80 AGL located 1900' N dep end Rwy 33. Sharp drop off both ends. No prepared shoulders. Sharp drop-off and/or soft gnd both sides of rwy. Thresholds marked with orange barrels. Possible extv heli t/c at aprt. See Galore Creek/Bob Quinn Lake VTPC.

