

QUEBEC

AERODROME / FACILITY DIRECTORY

LAC-À-LA-TORTUE QC

CSL3

| | | |
|-----------------|--|--|
| REF | N46 37 18 W72 37 49 2.6E 15°W (2015) UTC-5(4) Elev 434' A5002 | |
| OPR | Bel Air Laurentien Aviation Inc 819-538-8623 Reg | |
| PF | A-1 13-17Z† & 18-22Z† C-2,3,4,5,6 | |
| FLT PLN | (bil) FIC Québec 866-GOMÉTÉO or 866-WXBRIEF (Toll free within Canada) or 866-541-4105 (Toll free within Canada & USA) | |
| SERVICES | FUEL 100LL OIL All S 1,2,3,4,5,6 Bel Air Laurentien Aviation | |
| RWY DATA | Rwy 03/21 3000x40 ASPH Rwy 16/34 2000x40 ASPH RCR Opr 13-17Z† & 18-22Z† exc Sat & Sun. Dur thaw period (mid March to end of May) A/D NE sector may be flooded rendering rwys unserviceable. Rwy 03/21 no win maint. Rwy 16/34 ltd win maint. Ctc opr. | |
| COMM | (bil) ATF UNICOM ltd hrs O/T tfc 122.7 5NM 3500 ASL | |
| PRO | Mauricie Common Frequency Area. See Section C Planning. Seaplane tfc on adj lake. | |
| CAUTION | RWY: Cracks in Rwy 16/34. OBST: P-lines N of Thld 16 not lgtd. Four twrs up to 706 ASL (263 AGL) aprx 1.5NM NW A/D. BLASTING: Blasting ops, 0.4NM radius from N46 34 53 W72 43 44 (4.7NM WSW of A/D), max alt 2200 ASL. | |