

## ALBERTA

## AERODROME / FACILITY DIRECTORY

## HIGH RIVER / FOOTHILLS REGIONAL AIRPORT AB

CEN4

<b>REF</b>	N50 32 00 W113 50 27 2.5 SSE 14°E (2014) UTC-7(6) Elev 3447' VTA A5005 LO2 T1 CAP	
<b>OPR</b>	High River Regional Airport Ltd 403-601-1654 Reg	
<b>PF</b>	C-2,3,4,5,6	
<b>FLT PLN</b>		
<b>FIG</b>	Edmonton 866-WXBRIEF (Toll free within Canada) or 866-541-4102 (Toll free within Canada & USA)	
<b>ACC</b>	Edmonton IFR 888-358-7526	
<b>SERVICES</b>		
<b>FUEL</b>	100LL Foothills Flight Center Inc. 403-603-4091, JA-1 Murrays Aircraft Repair 403-648-8910 Self-serve, all major credit & debit cards	
<b>OIL</b>	All	
<b>S</b>	1,2,3,4,5,6	
<b>RWY DATA</b>	Rwy 07(066°)/25(246°) 4160x75 ASPH Thld 07 displ 687' Thld 25 displ 475' Rwy 15(145°)/33(325°) 2726x55 GRVL Rwy 33 down 1.28%	
<b>RCR</b>	Opr Ltd win maint Rwy 07/25. Ltd maint Rwy 15/33, sfc soft/ruf.	
<b>LIGHTING</b>	07-(TE LO), 25-(TE LO(holding bay not lgtd, not avbl for ngt ops)).	
<b>COMM</b>		
<b>MF</b>	Foothills tfc 123.0 5NM 6400 ASL (CAR 602.98)	
<b>PRO</b>	Practice auto-rotations and run-on landings by helis not auth on rwys. Caution dur hover ops at fuel centres due rotor wash. Air taxi ops preferred over infield areas whenever possible. Circuit tng flts proh 04-14Z† (CAR 602.96).	
<b>CAUTION</b>	Ultra-light activity on field. Acft at opposite ends of Rwy 07/25 may not be visible to each other. Wildlife in vic	