

Departure Route Description

All rwys: Maintain 5000 ASL or as assigned.

Rwy 06: Climb hdg 063° or as assigned.

Rwy 18: Climb hdg 182° or as assigned.

Rwy 24: Climb hdg 243° or as assigned.

Rwy 36: Climb hdg 002° or as assigned.

Communication Failure

On recognition of failure 10 minutes or less after take-off and in IFR weather conditions proceed as follows:

- 1. Select transponder code 7600;
- 2. Upon reaching assigned altitude proceed directly on course;
- 3. Maintain last assigned altitude for 10 minutes after take-off, then;
- 4. Climb to flight planned altitude.

Note: If communication failure occurs more than 10 minutes after take-off, comply with the appropriate procedures for communication failure enroute.

Source of Canadian Civil Aeronautical Data: © 2026 NAV CANADA All rights reserved